




Important Product Notice

When unmounted 5200 & 5300 series bearings are spun by hand, an audible clicking sound may be heard. This is due to the clearances internal to the bearing and **is normal**.

Radial Internal Clearance



The use of proper shaft and housing fits is critical for achieving reliable bearing performance. After this bearing assembly is mounted, loaded, and properly fitted in the application, the excess clearance will be removed and the bearing will operate properly.

Questions? Call Koyo's Tech Line at (866) Koyo-Tech or your local Koyo Rep.

June 2010

WWW.KOYOUSA.COM